

Work Order ID 98144

Thursday, April 11, 2013 2:16:33 PM

98144

Page 1

Item ID: D3926-3 Accept ***N9000040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Wedge
Start Date: 3/8/2013 Start Qty: 3.00 ***3*** Cust Item ID:
Required Date: 3/11/2013 Req'd Qty: 3.00 ***3*** Customer: CU-DAR001
Reference: RMA RA111491 *RETURN*

Approvals: Process Plan: *MC* Date: *13-4-11* Tooling: Date: Run Start ***NR1***
QC: Date: SPC (Y/N): Date: Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D3926	Rev A								

100 0.00

100

QC

Quality Control

Memo

INSPECT RA 111491 D 3926-3 X 3 B#94407

0.00

5/13/03/07

PARTS ARE GOOD

RETURN UNDER NEW BATCH NUMBER

110

Identify as per dwg & Stock Location: *8T203A* 0.00

110

Packaging

Packaging

Memo

ID AND STOCK UNDER NEW BATCH NUMBER

0.00

3x

SP 13-4-15

120

QC21- Final Inspection - Work Order Release 0.00

120

QC

Quality Control

Memo

0.00

13/4/16

13-4-16

Picklist Print

Thursday, April 11, 2013 2:16:32 PM

Page 1

Work Order ID: 98144

Parent Item: D3926-3

Parent Item Name: Wedge

Start Date: 3/8/2013

Required Date: 3/11/2013

Start Qty: 3.00

Required Qty: 3.00

Comments: IPP RevA: New issue DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3926-3 Wedge		Manufactured	No				Each	0.0000		3			

3 x 94407
MF
13-4-11

RA 111491 D3929-3 B94407

Received @ Dart March 6th, 2013
Inspected @ Dart March 7th, 2013

Customer: ERA HELICOPTERS LLC
Customer Contact: JINNIFER DINE
Shipped from: LAKE CHARLES LA, USA

Instructions for RA111491 D3929-3 B94407 Rev A

- Parts are D3929-3
- Return back into stock under new BATCH #
- Need work order to return back into stock
- Parts are still at Rev A

Time Estimate = 1 HOUR ONLY (stores)

Departments Required: Stores (restocking)

Pictures Attached = NO

QTY INSPECTED = x3 D3926-3

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**